


FIG. 1

09531850-032100

DKT 481-83


FIG. 2A



COMPONENT WITH SHORT, CAUSED BY EXCESSIVE EPOXY.

09531860 .032 29ax


MULTICHIP CERAMIC PACKAGE 28



R = measured
resistance
during temperature
ramp-up and ramp-down

FIG. 2B


Defective part with intermittent short (W1008)



09531850.032100

FIG. 3A
DKT 481-A3

Part W1008 after removal of short




Series 1

09531850 : 032400

FIG. 3B

PKT 481-AB

Defective epoxy contact on part (W1020)




— Series 1

FIG. 4

PKT 481-RB

00531850.032100

Part W1020 after repair of defective epoxy contact



— Series1

FIG. 5

09531850.032100

DKT 481-RB